

Cat. No. 2268-40

Infrared Temp-Gun™

TO REDUCE THE RISK OF INJURY, USER MUST READ AND UNDERSTAND OPERATOR'S MANUAL.

IMPORTANT SAFETY INSTRUCTIONS

WARNING READ ALL SAFETY WARNINGS AND INSTRUCTIONS. Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury. Save these instructions - This operator's manual contains important safety and operating instructions for the MILWAUKEE[®] Infrared Temp-Gun[™] Thermometer. Before using the Temp-Gun[™], read this operator's manual and all labels on the Temp-Gun[™].

LASER SAFETY

- •Laser light Do not stare into beam or view directly with optical instruments. Do not point laser light at others. Laser light can cause eye damage.
- •Avoid exposure to laser radiation. Laser may emit hazardous radiation.
- •Do not point laser at reflective surfaces. Unpredictable results may occur.

WORK AREA SAFETY

- •Keep children and bystanders away while operating Temp-Gun™. Store idle Temp-Gun™ out of the reach of children and do not allow persons unfamiliar with the tool or these instructions to operate them.
- •Avoid dangerous environments. Do not use in rain, snow, damp or wet locations. Do not use in the presence of explosive atmospheres (gaseous fumes, dust or flammable materials) because sparks may be generated when inserting or removing batteries, possibly causing fire.

PERSONAL SAFETY

- Stay alert, watch what you are doing and use common sense when operating Temp-Gun™.
 Do not use while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention may result in serious personal injury.
- •Do not overreach. Keep proper footing and balance at all times. This enables better control in unexpected situations.


BATTERY USE AND CARE

- •This tool is designed to be powered by one (1) 9V battery properly inserted into the *MILWAUKEE*[®] Temp-Gun[™]. Do not attempt to use with any other voltage or power supply.
- •Do not leave battery within the reach of children.
- •Install battery according to polarity (+ / –) diagrams.
- •Properly dispose of used batteries immediately.
- Do not incinerate or dismantle batteries.
- •Under abusive conditions, liquid may be ejected from the battery, avoid contact. If contact accidentally occurs, flush with water. If liquid contacts eyes, additionally seek medical help. Liquid ejected from the battery may cause irritation or burns.

SERVICE

- •Have your Temp-Gun[™] serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the tool is maintained.
- •Do not disassemble. Incorrect reassembly may result in the risk of electric shock or fire. If it is damaged, take it to the store where the product was originally purchased or one of our authorised *MILWAUKEE*[®] service centres.
- •Store in a cool, dry place. Do not store where temperatures may exceed 60°C (140°F) such as in direct sunlight, a vehicle or metal building during the summer.
- •Do not remove or deface labels. Maintain labels and nameplates. These carry important information. If unreadable or missing, contact the store where the product was originally purchased or one of our authorised *MILWAUKEE*[®] service centres.

FUNCTIONAL DESCRIPTION



SYMBOLOGY

V	Volts
	Direct Current
	CAUTION Laser Light - Do Not Stare Into Beam
	Laser product Avoid Exposure: Laser Radiation Is Emitted From This Aperture
8	To reduce the risk of injury, user must read operator's manual.

Specifications

IR Temperature range:

For 2268-40: -30°C to 550°C (-22°F to 1022°F)

IR Accuracy:

For 2268-40:

*Assume ambient operating temperature of 23°C ±2°C (70°F to 77°F)

Repeatability: ±0.8% OR ±1°C (±2°F) (whichever is greater) Temperature display resolution: 0.1°C/°F in Primary and Secondary Distance to spot (90% energy):

For 2268-40: 12 to 1 Emissivity: 0.95 Response time:<500 msec Spectral response: 8 to 14µm Drop: 2 meters Laser Type: Class II Max Power: <1mW Wavelength: 630-670 nm Operating temperature: 0°c to 50°C (32°F to 122°F) Storage temperature: 0°c to 60°C (-4°F to 140°F) without battery Relative humidity: 10 to 85% at 25°C, decreasing linearly to 10 to 45% at 50°C Voltage: 9 DC (one (1) 9V battery) Battery life: Greater than 12 hrs with all functions

NOTE: The product may not meet its stated accuracy when exposed to 80-500MHz at 3V/m.

ASSEMBLY

Loading/Changing the Battery

- Using a flat screwdriver, rotate the battery door lock to the unlocked position and open the battery door.
- Connect one (1) 9V battery to the connector block. Fit the battery into the compartment.
- Close the battery door.
 Turn the battery door lock to the locked position.

Selecting Celsius or Fahrenheit

To set the temperature scale, pull the trigger and then press the SET button three times. Press the buttons above the up and down arrows to toggle between °C and °F. Wait 5 seconds for the setting to save and exit.

Setting the Laser Lock

To turn the laser on and off, pull the trigger and then press the SET button four times. Press the buttons above the up and down arrows to toggle between ON and OFF. Wait 5 seconds for the setting to save and exit.



Center of Spot Distance to Spot: - – Laser pointer (approx. 19 mm above center of spot) 12:1 (2268-40) Spot size at distance indicated NOTE: A quick change in temperature (>10°F) affects the meter's readings. Allow the meter to reach ambient temperature before use (5 to 30 minutes, depending on temperature change). 2268-40: At 30 cm away, spot is 38 mm in diameter

2268-40: At 90 cm away, spot is 76 mm in diameter

2268-40: At 150 cm away, spot is 127 mm in diameter

Scanning Object Temperature

1. Pull and hold the trigger for at least 2 seconds and scan the surface temperature of an object. A laser pointer is used for aiming on the area being scanned. A

NOTE: The object should be larger than the spot being scanned. If not, readings will be affected. See Distance To Spot for necessary object size.

- 2. As you continue to hold the trigger, the icon A is displayed along with the primary measurement (surface temperature) and secondary measurement (maximum, minimum, average, or differential temperature) readings.
- 3. Release the trigger. HOLD is displayed until the screen shuts off in about ten seconds.

Setting the Trigger Lock

To turn the trigger lock on and off, pull the trigger and then press the SET button five times. Press the buttons above the up and down arrows to toggle between ON and OFF. Wait 5 seconds for the setting to save and exit.

temperature reading will flash. Setting Preset Range for the Alarm

Temperature Alarm

- 1. To set the alarm range, pull the trigger and then press the SET button. Repeat to toggle between HI and LO settings.
- 2. Press the up or down arrow soft keys to toggle between temperatures. Wait 5 seconds for the ranges to save and exit.

Low Battery

When the Low Battery icon is displayed, change the battery.




	1.0.3
Mode	Description
MAX	Displays maximum temperature measured during a continuous reading
MIN	Displays minimum temperature measured during a continuous reading
AVG	Displays average temperature of last 20 measurements during a continuous reading
DIF	Displays the difference between MAX and MIN during a continuous reading



the alarm function. The bell icon is displayed. If the temperature reading is outside the preset range, the

OPERATION



Ļ

MAINTENANCE

WARNING To reduce the risk of injury, always remove the batteries from the tool before performing any maintenance. Never disassemble the tool. Contact a *MILWAUKEE*[®] service facility for ALL repairs.

Maintaining Tool

Keep your tool in good repair by adopting a regular maintenance program. After six months to one year, depending on use, return the tool to the store where the product was originally purchased or one of our authorised *MILWAUKEE*[®] service centres.

If the tool does not start or operate at full power with new batteries, clean the contacts on the battery door. If the tool still does not work properly, return the tool to the store where the product was originally purchased or one of our authorised *MILWAUKEE*[®] service centres.

Cleaning the Lens

Blow off loose particles with clean compressed air. Carefully wipe the suface with a cotton swab moistened with water. Using a second cotton swab, dry completely.

WARNING To reduce the risk of personal injury and damage, never immerse your tool in liquid or allow a liquid to flow inside it.

Cleaning

Clean dust and debris from tool. Keep tool handles clean, dry and free of oil or grease. Use only mild soap and a damp cloth to clean the tool since certain cleaning agents and solvents are harmful to plastics and other insulated parts. Some of these include gasoline, turpentine, lacquer thinner, paint thinner, chlorinated cleaning solvents, ammonia and house hold detergents containing ammonia. Never use flammable or combustible solvents around tools.

Repairs

For repairs, return the tool to the nearest service center listed on the back cover of this operator's manual.

ACCESSORIES

WARNING Always remove batteries before changing or removing accessories. Only use accessories specifically recommended for this tool. Others may be hazardous.

For a complete listing of accessories refer to your *MILWAUKEE*[®] accessories catalogue or go online to www.milwaukeetools.com.au or www.milwaukeetools.co.nz. To obtain a catalogue, contact the store where the product was originally purchased or one of our authorised *MILWAUKEE*[®] service centres.

WARRANTY - AUSTRALIA and NEW ZEALAND

Please refer to Australian and New Zealand warranty supplied with the tool. This warranty applies only to product sold in Australia and New Zealand.

AUSTRALIA AND NEW ZEALAND MILWAUKEE[®] SERVICE

MILWAUKEE[®] prides itself in producing a premium quality product that is Nothing But Heavy Duty[®]. Your satisfaction with our products is very important to us! If you encounter any problems with the operation of this tool, please contact your authorised MILWAUKEE[®] dealer. For a list of *MILWAUKEE[®]* dealers, guarantee or service agents please contact *MILWAUKEE[®]* Customer Service or visit our website.

Australia: 1300 MILWAUKEE (1300 645 928) www.milwaukeetools.com.au New Zealand: 0800 279 624 www.milwaukeetools.co.nz

Milwaukee Electric Tool Corporation

13135 West Lisbon Road, Brookfield, Wisconsin U.S.A. 53005

Milwaukee Electric Tool Corporation (Australia)

Techtronic Industries (Australia) Pty. Ltd. Rowville, Victoria, Australia, 3178

Milwaukee Electric Tool Corporation (New Zealand)

Techtronic Industries (New Zealand) Pty. Ltd. Mangere, Auckland, New Zealand, 2022

Professionally made in China for Milwaukee Electric Tool Corporation